

WARRANTY INFORMATION SERVICE INFORMATION Bulletin No. 2002-03
 PARTS INFORMATION

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager


Motor Assembly Part Number Change

Models Affected

All 1990-1996 Hand and Foot Models


Situation

Hand Models: Motor assembly part number MCF397102 is No Longer Available (NLA). In order to replace the motor it is necessary to use motor assembly MCF397172. Use of this motor will also require installing a new board assembly (MAT15701) and a new handle assembly (MAT372052). Use the following wiring diagram to complete the installation of the new components.



THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE. This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Foot Models: Motor assembly part number MCF397112 is No Longer Available (NLA). In order to replace the motor it is necessary to use motor assembly MCF397182. Use of this motor will also require installing a new board assembly (MAT15704). Use the following wiring diagram to complete the installation of the new components.



Parts Required

HAND MODELS

Qty.1	MCF397172	Motor Assembly
Qty.1	MAT15701	Board Assembly
Qty.1	MAT372052	Handle Assembly

FOOT MODELS

Qty.1	MCF397182	Motor Assembly
Qty.1	MAF15704	Board Assembly

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.